

SOLIDWORKS COMMANDS

Browse Recent DocumentsR
Shortcut BarS
Confirmation Corner/BreadcrumbsD
Command SearchW
RebuildCtrl + B
Force Regen.....Ctrl + Q
Delete Delete
Repeat Last CommandEnter
Task Pane.....Ctrl + F1
Toggle Selection Filter ToolbarF5
Toggle Selection Filter Type.....F6
Spell CheckF7
ToolbarsF10
Full ScreenF11
Hide Component under Mouse.....Tab
Show Component under Mouse....Shift + Tab
Dimension to Arc Min/Max Shift LBM
Tangent Arc ToggleA

SOLIDWORKS VIEW COMMANDS

Zoom to FitF
Orientation Spacebar
View CubeCtrl + Spacebar
Front.....Ctrl + 1
BackCtrl + 2
LeftCtrl + 3
RightCtrl + 4
Top.....Ctrl + 5
Bottom.....Ctrl + 6
IsometricCtrl + 7
Normal To.....Ctrl + 8
Undo View ChangeCtrl + Shift + Z
Zoom InShift + Z
Zoom OutZ
Area Magnify.....G

WINDOWS COMMANDS

New.....Ctrl + N
Open.....Ctrl + O
Close WindowCtrl + W
Close FileCtrl + F4
Close SOLIDWORKSAlt + F4
Swap WindowsCtrl + Tab
SaveCtrl + S
Print.....Ctrl + P
Find/ReplaceCtrl + F
Select All.....Ctrl + A
CutCtrl + X
CopyCtrl + C
Paste.....Ctrl + V
Undo.....Ctrl + Z
RedoCtrl + Y



SOLIDWORKS

Keyboard & Mouse Quick Reference Guide



MOUSE BUTTON CLICKS

LMB = Left Mouse Button
MMB = Middle Mouse Button
RMB = Right Mouse Button

SOLIDWORKS MOUSE GESTURES

Select Fully Enclosed EntitiesLMB Drag Left to Right
Select Intersected Entites.....LMB Drag Right to Left
Select a RangeHold Shift + LMB Click
Select or Deselect Entities.....Hold Ctrl + LMB Click
Pan.....Ctrl + MMB Drag
Translate Assembly Component..... LMB Drag
Zoom about Pointer MMB Scroll
Zoom about Center.....Shift + MMB Drag
Rotate.....MMB Drag
Rotate Assembly Component..... RMB Drag
Rotate Normal to Screen Alt + MMB Drag
Smart MatesAlt + LMB Drag