

POLYJET DESKTOP MAINTENANCE PACKAGES

	DIAMOND	EMERALD*
Telephone/Email Support	⊘	⊘
All Machine Parts Included	⊘	⊘
Labor Included	⊘	⊘
Preventative Maintenance Visit	⊘	⊘
SW/HW Upgrades	⊘	⊘
Downtime Support	⊘	
Service Consumables	⊘	
One SHR Print Head Replacement	⊘	
MAINTENANCE CONTRACT TIERS		
Objet 24	\$4,500	\$3,000
Objet 30/30 Pro/30 Prime	\$4,500	\$3,000
J55	\$10,500	\$7,900

Phone/Email Support | Monday - Friday

Digital Manufacturing Technical Support

Telephone: 855.470.0647 Email: AMsupport@goengineer.com

Telephone: 855.470.0647 Email: supplies@goengineer.com



MAINTENANCE PACKAGE DETAILS

Telephone/Email Support | Monday - Friday

Digital Manufacturing Technical phone/email support

Telephone: 855.470.0647 Email: AMsupport@goengineer.com

Digital Manufacturing Consumables phone/email support

Telephone: 855.470.0647 Email: supplies@goengineer.com

All Machine Parts are Included (Excluding Parts Deemed Consumables by Stratasys)

- All software and firmware updates to the systems are included.
- Software updates for PolyJet products are provided at GoEngineer discern and can be combined with on-site visit for repair or maintenance (excluding optional updates).
- Wash station and secondary/post processing systems are not included with the printer maintenance

Diamond Care Service Consumables

- Diamond Care Order Form must be completed and submitted to MaterialsOrders@stratasys.com to be included in the Diamond Care maintenance
- See Diamond Care Order Form for a complete list of service consumables.

Labor Included

Labor for diagnosing, repair or maintenance included.

- On-site service visits occur when GoEngineer determines, in its sole discretion, that phone and email support cannot be rendered to resolve the problem.
- Assistance from customer with diagnosing and performing tests is required within a reasonable amount of time as to allow GoEngineer to make the determination of the necessity of an on-site visit.

Preventative Maintenance Visit

Visit performed once a year to check on normal wear and tear of the machine.

Maintenance visits will usually occur somewhere between month 9–12 on a full contractual year (based on maintenance start date). Preventative maintenance visit must be completed before maintenance terms expire.

PM Visit Includes

- Firmware/Software check/upgrade.
- Replacement of vital filters, pump tubing, wiper, roller blades.
- Calibration of all of the components of the machine: UV light, vacuum, print heads, wiper, roller.
- Customer will need to provide GoEngineer with normal machine use accessories at time of visit (isopropyl alcohol, lint free cloths, latex gloves, etc.)

TO GOERGINEER | SUPPORT

MAINTENANCE PACKAGE DETAILS

Downtime Support

- Diamond Care Customers can outsource 3D part builds to GoEngineer after it is determined that their machine will be down for two (2) full business days after proper notification to GoEngineer.
- Notification to start two (2) business days time frame must include all required information (pictures, logs, files, description) and must be before cut off time of 2pm M-F to start clock—GoEngineer has a requirement that customers must perform requested diagnostics and tests to be performed in a reasonable amount of time in order for GoEngineer to determine that the machine will not be running prior to two (2) business days.
- Parts will be 3D printed with the first available model material on the first available PolyJet machine and shipped with support material still on. Specific material requests cannot be guaranteed and may incur additional costs or delays.
- Biocompatible and dental materials are not available for downtime support.
- Parts are shipped standard one day, if needed sooner customer will have to pay for alternative shipping methods.
 - Polyjet parts are not recommended to be shipped over the weekend due to warping risks and extreme temperatures, decision is made by customer's own discretion.
- GoEngineer reserves the right to substitute materials with similar material characteristics to expedite 3D printing.
- Material, quantity, and size of parts built must be equivalent to customer's down machine capabilities.
- Once GoEngineer determines that customer machine is back up and running, downtime support ceases immediately, and no new builds will be started, regardless of builds in queue.

Exclusions or Delays For Downtime Guarantee Include (But Are Not Limited To)

- Lack of performing tests within reasonable time frame.
- Issues caused by lack of proper calibration, cleaning, maintenance, or other customer responsibilities.
- Issues caused by normal consumable part wear.

Travel Fees

- Travel Charge (100 499 miles outside a GoEngineer office) \$500
 - This applies for any visit, including preventative maintenance visits.
 - For repair visits with customers on maintenance, this charge applies on a "per incident" basis.
- Travel Charge (500+ miles outside a GoEngineer office) \$1,000
 - This applies for any visit, including preventative maintenance visits.
 - For repair visits with customers on maintenance, this charge applies on a "per incident" basis.

Recertification Process / Fee (\$1,500)

- Machine must be in good working condition
 - Identifying and repairing defective parts are required priror to a new maintenace contract
 - Recertification fee is waived if a new contract is put in place within 30 days after a repair.
 - *Working condition, meaning the system is operational. This includes but is not limited to the following: the printer is not missing parts, has not been dismantled, and/or has not sustained major damage, and the major components of the system (such as the mechanical and electrical components) function properly."
 - Replacement parts ordered within 30 day days of the recertification are not covered under the maintenance contract.
- Stratasys requires a Recertification Acknowledgement Letter to verify recertification eligibility.

Water Jet System, 110V-120V 60Hz – Parts Only (\$200) Water Jet System, OWJ-01US 110V-120V 60Hz – Parts Only (\$200)

- Customer may requests an on-site visit for the cleaning station—Standard travel plus labor charge.
- Customer can pay for shipment to and from a RP technician staffed GoEngineer office No travel charge.
- Cleaning station serviced during a printer on-site visit—No additional travel charge.

DISCLAIMER NOTICE TO CUSTOMER //